

LEASE FACILITY INSPECTION REPORT

Serial Num 142732	Date October 23, 2026	Operator Texas Petroleum Investment Company	Id T029
Lease Name BIG N 1 RB SUA;C E GHEENS # 089		Address 1497 Clear Creek Church Rd	
Section: 037	Township: 15S	Range: 20E	Lumberton , MS 39455-
Parish LAFOURCHE			
Field Bayou Des Allemands	Id: 0693	Contact Connie Gipson	

A. INSPECTION REASON

Request by Baton Rouge Office

Complaint #:

Order #:

B. WELL SITE

1. IDENTIFICATION: Passed

2. CONDITION: Deficiency

Violation(s): E&P Waste At Ws

Violation(s): Oil At Ws

Violation(s): Wellhead Not Maintained

Well Site Comments: received call from losco about well leak in field, appears casing is broken below water line leaking oil & gas, well is leaning, well site boomed off & canals, clean up crew on site (see photos) incident # 26-03603

Well Accessibility: ACCESSIBLE**Transportation to Site:** BOAT**C. TANK BATTERY** None**D. FIRE HAZARD** Deficiency

Violation(s): E&P Waste Discharge - Live Oil Fire Hazard

Fire Comments: live oil at well**E. DISCHARGE OF E&P** Deficiency

Violation(s): E&P Waste Discharge

Discharge Status: Present**Discharge Comments:** well leaking**F. DISPOSITION OF E&P****Site Id:****Site Name:****G. EXISTENT PITS:** No**REMARKS:**

THE OPERATOR'S REPRESENTATIVE SHALL SIGN THIS REPORT TO ACKNOWLEDGE RECEIPT OF HIS COPY, YOUR SIGNATURE CANNOT BE CONSTRUED AS AN ADMISSION OF GUILT FOR ANY VIOLATIONS CONTAINED IN THIS REPORT.

No Witness

October 23, 2026

IN COMPLIANCE No**Sealed:** N

Operator's Representative

KEITH ADAMS

October 23, 2026

Sonris Id: 983667

LEASE FACILITY INSPECTION REPORT

Conservation Enforcement Agent

Latitude (Deg/Min/Sec:) 29 45 48.4 Longitude (Deg/Min/Sec:) 90 23 21.8

**Subject:** casing damage below water linePhoto File Name: [2068574242802950879/SN # 142732 CASING CORR](#)**Subject:** oil in grassPhoto File Name: [2068576658865953769/SN # 142732 OIL IN WATER](#)**Subject:** oil in waterPhoto File Name: [2068581565064958489/SN # 142732 OIL IN WATER.](#)

LEASE FACILITY INSPECTION REPORT

SRCN9960



Subject: well leaking

Photo File Name: [2068583696749960749/SN # 142732 WELL LEAKING](#)



Subject: sign

Photo File Name: [2068587255310962982/SN # 142732.jpg](#)